



BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	Street Name	Significant Landmark
W1302	2nd Crs	Akashavani Layout
Segment No.	Total Length (m)	
6/S-W1302/S051324	336.81	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	336.81	77.612455	13.053140	77.615105	13.053297	W0688	W1079

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvement to Roads and Drains at Akashavani Layout Dasarahalli in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	1300000	2015
Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	
Tender	Work Details	Job No. / Work Code
Tender	Improvement to Roads and Drains at Akashavani Layout Dasarahalli in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	006-15-000031
Work Order No.	Work Order Date	Period of Extention
EE/BTP/BBMP/E-PMT/WO/326/2015-16	24/03/2016	90 DAYS
Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
24/03/2016	23/03/2017	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
CHENNAKRISHNA.P		0.00
Phone No.	E-Mail ID	
9741713358		

Field Inspection Details

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W1302

Number of Trees

0

Any Other Information**Name**

KRISHNAPPA

Date of Inspection

29/10/2016

Remarks

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA**Ward No:** 6**Ward Name:** Thanisandra**Street ID:** W1302

Date: 29/10/2016

Time: 18:28:12

RH 20161029182812

Page 2 of 3

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks				
Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAI AH	29/10/2016	28/11/2016	COMPLETED
SE	VASU K M	29/10/2016	28/11/2016	COMPLETED
EE	YARAPPA REDDY	29/10/2016	28/11/2016	COMPLETED
AEE	J N LOKESH	29/10/2016	28/11/2016	COMPLETED
AE	KRISHNAPPA	29/10/2016	28/11/2016	COMPLETED
AE	KRISHNAPPA	29/10/2016	28/11/2016	COMPLETED